



Photo 1 – Front view of airplane with portion of separated nose landing gear.



Photo 2 – Damage to the top of the cowling.



Photo 3 – Deformation in fuselage above wing root.



Photo 4 – View of ground scar from left of the runway towards the ramp.