



Photo 1 – Main Wreckage – Courtesy of Skyland Fire Rescue



Photo 2 – Rear View of Main Wreckage – Courtesy of Skyland Fire Rescue



Photo 3 – Close Up of Main Wreckage – Courtesy of Skyland Fire Rescue



Photo 4 – Front View of Propeller and Engine



Photo 5 – Propeller Blade Tip



Photo 6 – Other Propeller Blade Tip



Photo 7 – Right Side View of Propeller and Engine



Photo 8 – Left Side View of Engine



Photo 9 – Forward Cabin Area



Photo 10 – Throttle, Propeller, and Mixture Control Cables



Photo 11 – Fuel Selector Valve



Photo 12 – Oil Level Gauge (Dipstick)



Photo 13 – Air Intake Filter




Photo 14 – Left Side View of Engine After Cylinder Removal



Photo 15 – Close Up of Crankshaft (No. 4 Cylinder Position)



Photo 16 – Remains of No.4 Connecting Rod




Photo 17 – Oil Pump Drive Gear




Photo 18 – Interior of Oil Pump



Photo 19 – Engine Oil Sump



Photo 20 – Contents of Engine Oil Sump