




Photo 1 – View of the airplane at the accident site in trees (Photo Courtesy FAA)



Photo 2 – View of the airplane at the accident site (Photo Courtesy of FAA)



Photo 3 – View of the airplane engine compartment area and propeller (Photo Courtesy FAA)



Photo 4 – View of the airplane's right wing (Photo Courtesy FAA)



Photo 5, 6 – View of the airplane's left wing (Photo Courtesy FAA)




Photo 7-10: Overview of the exterior of the engine