



Photo 1 – Electric Motor Carbon Brush (-)



Photo 2 – Electric Motor Carbon Brush (+)



Photo 3 – Commutator



Photo 4 - Armature



Photo 5 – Area of Broken Wire