



Investigative Photographs

ERA20LA082

Peter Wentz

Air Safety Investigator

Eastern Region Aviation

Photographs provided by the FAA



Photograph 1 – Accident airplane – right side view.



Photograph 2 – Accident airplane – forward right view.



Photograph 3 – Accident airplane – engine, propeller, and cowling.



Photograph 4 – Accident airplane – forward left view at recovery location.