



Photo 1 – Previous Damage to Balloon – Courtesy of Annette Dominguez



Photo 2 – Enroute – Courtesy of Annette Dominguez



Photo 3 – Enroute – Courtesy of Annette Dominguez



Photo 4 – Enroute – Courtesy of Karen Smith



Photo 5 – Enroute – Courtesy of Karen Smith



Photo 6 – Enroute – Courtesy of Karen Smith



Photo 7 – Enroute – Courtesy of Karen Smith



Photo 8 – Ground Chase Team – Courtesy of Karen Smith



Photo 9 – Enroute – Courtesy of Karen Smith



Photo 10 – Accident Site – Courtesy of Karen Smith



Photo 11 – Burned and Torn Skirt – Courtesy of Karen Smith



Photo 12 – Basket – Courtesy of Gina Falish Uhle



Photo 13 – Floor of Basket – Courtesy of Gina Falish Uhle