



Photo 1 – View of airplane wreckage resting in tree. Note right wing damage. (Courtesy of FAA)



Photo 2 –Closeup view of severely deformed left wing. (Courtesy of FAA)



Photo 3 – View of airplane wreckage after successful engine operation.