



MEMORANDUM FOR RECORD

Investigative Photographs

ERA20LA126

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1 – Accident site (photo provided the FAA).



Photograph 2 – Accident airplane – Right side of airplane in tree (photo provided the FAA).



**Photograph 3 – Accident airplane – Right side cockpit door and engine.
(Photo provided Beverly Flight Center).**



**Photograph 4 – Accident airplane –Right side engine.
(Photo provided Beverly Flight Center).**



**Photograph 5 – Accident airplane – Cockpit instrument panel (Carb Ice light).
(Photo provided Beverly Flight Center).**



**Photograph 6 – Accident airplane – Cockpit instrument panel (Carb Ice sensitivity control).
(Photo provided Beverly Flight Center).**