



Photo 1 – View of Initial Ground Scar and Main Wreckage (FAA)



Photo 2 – View of Linear Ground Scar (FAA)



Photo 3 – View of Main Wreckage as Found (FAA)



Photo 4 – View of Tow Rope (FAA)