



Photo 1 – View of the wreckage where it came to rest. (Photo courtesy of the FAA)



Photo 2 – View of the left side of the wreckage. (Photo courtesy of the FAA)



Photo 3 – View from the empennage looking forward towards the nose. (Photo courtesy of the FAA)



Photo 4 – View of the engine and propeller. (Photo courtesy of the FAA)