



Photo 1 – Overall view of airplane as it rests shortly after landing. (Courtesy of FAA)



Photo 2 – View of right engine and propeller damage. (Courtesy of FAA)



Photo 3 – View of right flap damage. (Courtesy of FAA)



Photo 4 – View of left side of airplane damage. (Courtesy of FAA)



Photo 5 – Left landing gear fractured scissors. (Courtesy of FAA)



Photo 6 – Closeup of fracture on left landing gear scissors. (Courtesy of FAA)



Photo 7 – Cockpit emergency gear handle. (Courtesy of FAA)