



Photo 1 – View of airplane from left side showing left wing damage



Photo 2 – View of right wing showing buckling damage



Photo 3 – View of left side of fuselage showing buckling damage