



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20LA207



Photo 1 – View of airplane from left wing (Photo Courtesy of FAA)



Photo 2 – View of airplane from rear (Photo Courtesy of NY State Police)



Photo 3 – View of airplane from right wing (Photo Courtesy of FAA)



Photo 4 – View of airplane from front (Photo Courtesy of FAA)



Photo 5 – Close-Up view of engine and empennage (Photo Courtesy of NY State Police)



Photo 6 – View of propeller hub (Photo Courtesy of FAA)



Photo 7 – View of Propeller (Photo Courtesy of FAA)



Photo 8 – View of propeller damage (Photo Courtesy of FAA)



Photo 9 – Center ballast bag (Photo Courtesy of FAA)



Photo 10 – Left ballast bag (Photo Courtesy of FAA)



Photo 11 – Right ballast bag (Photo Courtesy of FAA)



Photo 12 – View of rudder pedals and ballast (Photo Courtesy of FAA)