



MEMORANDUM FOR RECORD

Investigative Photographs
ERA20LA216

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Federal Aviation Administration.



Photograph 1 – Accident Site – Front left view of helicopter.



Photograph 2 – Accident Site – Tail boom and tail rotor.




Photograph 3 – Accident Site – Tail boom and tail rotor.



Photograph 4 – Accident helicopter – Post accident examination of tail rotor.



Photograph 5 – Accident helicopter – Post accident examination of tail rotor.



Photograph 6 – Accident helicopter – Post accident examination of rotor blades.



Photograph 7 – Accident helicopter – Post accident examination of rotor blades.