




Photo 1 – Overview of accident site showing location of wire and helicopter wreckage location.



Photo 2 – View of pole and hunting stand that the wire was attached to. (Courtesy of FAA)



Photo 3 – View of front right side of helicopter showing damage to the fuselage and cockpit. (Courtesy of FAA)



Photo 4 – Close up view of wire wrapped around the mast. (Courtesy of FAA)



Photo 5 – Close up view of damaged rotor blade. (Courtesy of FAA)



Photo 6 – View from inside damaged cockpit looking forward. (Courtesy of FAA)



Photo 7 – Left front quarter view of helicopter damage. (Courtesy of FAA)



Photo 8 – View of right aft side of helicopter from the direction of travel through the corn. Note the wire wrapped around the rotor blades. (Courtesy of FAA)



Photo 9 – View of separated empennage. Note: tail rotor separated during impact. (Courtesy of FAA)