



Photo 1 – Front View of Accident Airplane – Courtesy of Exeter Township Police Department



Photo 2 – Right Rear View of Airplane – Courtesy of Exeter Township Police Department



Photo 3 – Left Rear View of Airplane – Courtesy of Exeter Township Police Department



Photo 4 – Left Wingtip – Courtesy of Exeter Township Police Department



Photo 5 – Damage to First Automobile – Courtesy of Exeter Township Police Department



Photo 6 – Damage to Second Automobile – Courtesy of Exeter Township Police Department



Photo 7 – Damage to Right Wingtip – Courtesy of FAA



Photo 8 – Damage to Left Horizontal Stabilizer – Courtesy of FAA



Photo 9 – Damage to Left Lower Fuselage – Courtesy of FAA



Photo 10 – Damage to Left Upper Fuselage – Courtesy of FAA



Photo 11 – Buckled Left Side Cabin Floor – Courtesy of FAA



Photo 12 – Damage to Right Lower Fuselage – Courtesy of FAA