



Photo 1 – Digital Photograph from FAA. Front View of the Airplane At the Accident Site. Note the substantial Damage to Both Wings.



Photo 2 - Digital Photograph from FAA. Right Side View of the Airplane At the Accident Site. Note the substantial Damage to The Right Wing and Empennage.



Photo 3 - Digital Photograph from FAA. Close-Up Frontal View of the Propeller and Portions of the Fuselage and Both Wings At the Accident Site. Note the Damage to The Propeller Spinner and Scratches to the Propeller.



Photo 4 - Digital Photograph from FAA. Right Side View of the Airplane During the Operational Test of The Engine.