



Photo 1 – View of front of airplane resting on embankment nose down. (Courtesy of FAA)



Photo 2 – View of right wing damage. (Courtesy of FAA)



Photo 3 – View of left wing damage as it rest up against a tree. (Courtesy of FAA)



Photo 4 – View of left underside of wing and fuselage damage. (Courtesy of FAA)



Photo 5 – Screen capture of video that shows airplane travelling towards the trees on the left. (Courtesy of Newnan, Coweta County)