



Photo 1 – Front View of Main Wreckage (Photo Courtesy of Piper)



Photo 2 – Rear View of Main Wreckage (Photo Courtesy of Piper)




Photo 3 – Left Side of Engine (Photo Courtesy of Piper)




Photo 4 – Number Four Cylinder (Photo Courtesy of Lycoming)