



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20LA312



Photo 1 – View of airplane where it came to rest. (Photo Courtesy of FAA)



Photo 2 – View of right side of airplane (Photo Courtesy of FAA)



Photo 3 – View of fire damaged engine and fuselage. (Photo Courtesy of FAA)



Photo 4 – Grass strip pilot departed from and the direction of travel. (Photo Courtesy of FAA)