



**Photo 1 – Digital Photograph Provided by FAA. Right Forward Quartering View of the Airplane at the Accident Site.
Note the Separated Outer Section of the Left Wing.**



Photo 2 - Digital Photograph Provided by FAA. Left Side View of the Airplane at the Accident Site. Note the Separated Outer Section of the Left Wing.




Photo 3 - Digital Photograph Provided by FAA. View Showing Separated No. 2 Cylinder From the Crankcase.




Photo 4 - NTSB Digital Photograph. View Showing the No. 2 Cylinder Pad of the Crankcase. Note the heat Discoloration of the Connecting Rod Consistent with Lack of Lubrication.