



Photo 1 – Main wreckage, front right view



Photo 2 – instrument panel



Photo 3 – left front view



Photo 4 – Engine, hole in case at #2 cylinder



Photo 5 – Hole at #2 cylinder case.