

Bob Troup

PA 28-151

N 3385-9

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6-15-17	Tach 7180.6 TLE 7180.6 SMCH 149.8	#1- ²³ / ₈₀ , #2- ¹⁸ / ₈₀ , #3- ¹⁹ / ₈₀ , #4- ²⁰ / ₈₀ . R&R #1 & #4 cylinders and cleaned and lapped exhaust valves. Cleaned and rotated plugs. Changed oil and filter. Serviced with 7 qts Aeroshell 11 151cc oil. After repair: #1- ¹⁴ / ₈₀ , #2- ¹⁸ / ₈₀ , #3- ¹⁶ / ₈₀ , #4- ¹⁷ / ₈₀ . I certify this engine has been inspected IAD an annual inspection and is airworthy. END [redacted] IA [redacted] Long T. Selley, Jr.		

DATE 19__	RECORDING TACH TIME
--------------	---------------------------

I had seen both
birds at the same
place before.
under cliffs all
throughout (all)
the old country.
I saw one elsewhere
at present. H. & C. (H.)
say I did see
one before. I did
not know it was
under the rocks
before.

Larry J. So. Ky. Tr.

