



Photo 1 – Digital Photograph Provided by FAA. Right Side View of the Airplane Before Recovery.



Photo 2 - Digital Photograph Provided by FAA. View of Bottom of Fuselage Taken Behind Main Landing Gear Looking Forward. Note the Structural Damage.