



Weather Observations

11 Miles NW of Accident Site

Aaron McCarter
Air Safety Investigator
Eastern Region Aviation

October 3, 2019

METAR/SPECI from KBOW, Bartow Municipal (United States).

SA 03/10/2019 17:50->	METAR KBOW 031750Z 07010KT 10SM SCT035 32/19 A2998=
SA 03/10/2019 16:50->	METAR KBOW 031650Z 06010KT 10SM SCT030 31/19 A3001=
SA 03/10/2019 15:50->	METAR KBOW 031550Z 06008KT 10SM BKN025 29/20 A3002=
SA 03/10/2019 14:50->	METAR KBOW 031450Z 06010KT 10SM BKN020 29/21 A3002=
SP 03/10/2019 14:30->	SPECI KBOW 031430Z 06008KT 10SM BKN015 28/22 A3002=
SP 03/10/2019 14:10->	SPECI KBOW 031410Z 07008KT 10SM SCT012 28/22 A3002=
SA 03/10/2019 12:50->	METAR KBOW 031250Z 04004KT 10SM SKC 25/22 A3001=
SA 03/10/2019 11:50->	METAR KBOW 031150Z 00000KT 10SM FEW010 22/21 A2999=
SA 03/10/2019 11:30->	METAR KBOW 031130Z 04004KT 10SM FEW010 21/20 A2999=
SA 03/10/2019 11:15->	METAR KBOW 031115Z AUTO 03005KT 10SM CLR 21/20 A2999 RMK AO2=
SA 03/10/2019 10:55->	METAR KBOW 031055Z AUTO 00000KT 10SM FEW022 20/19 A2998 RMK AO2=
SA 03/10/2019 10:35->	METAR KBOW 031035Z AUTO 00000KT 10SM SCT022 20/19 A2997 RMK AO2=
SA 03/10/2019 10:15->	METAR KBOW 031015Z AUTO 00000KT 10SM SCT021 21/21 A2997 RMK AO2=