



Photo 1 – Overhead view of accident site from about 150 feet agl. Note police helicopter that attempted to rescue pilot about 100 feet to the right of gyroplane; See ERA20LA004. (Courtesy of FAA)



Photo 2 – Overhead view of left side of gyroplane in the mud showing damage to the rotor blade. (Courtesy of FAA)



Photo 3 – Overhead view of gyroplane in the grass and mud. Note the damaged rotor blade (Courtesy of FAA)



Photo 4 – Photograph of interior of cockpit and fuselage buckling. (Courtesy of FAA)



Photo 5 – Damage to rotor mast and propellers. (Courtesy of FAA)



Photo 6 – View of contaminated fuel drained from gyrocopter on left compared to clean fuel on right. (Courtesy of FAA)