



Photo 1 – Wreckage Path (NTSB)



Photo 2 – Main Wreckage at Accident Site (NTSB)



Photo 3 – Main Wreckage and Engine at Accident Site (NTSB)



Photo 4 – Engine and Propeller at Accident Site (NTSB)



Photo 5 – Cloudy Water Found in Airframe Fuel Filter (NTSB)



Photo 6 – Airframe Fuel Filter Bowl (NTSB)



Photo 7 – Airframe Fuel Filter Screen (NTSB)