



Photo 1 –View of airplane wreckage as discovered. Left wing nearly vertical and right wing detached and resting beside wreckage on ground.



Photo 2 – View of wreckage looking down right wing towards bottom side of fuselage.



Photo 3 – View of right side of rudder, elevator and stabilizer damage.



Photo 4 – View from pilot seat, cockpit instrument panel and rudder pedals.



Photo 5 – View of left wing damage. Note: Wing remained attached to fuselage and was oriented in a vertical position.



Photo 6 – View of left cowl that opened during takeoff.



Photo 7 – View of fuel gascolator in wreckage. Note: contained fuel.



Photo 8 – View of a 6-inch diameter branch that contained a distinct propeller slash indication.



Photo 9 – Overall forward view of wreckage during recovery. Note damage to cockpit, propeller and left wing.



Photo 10 – View of engine and fuselage on test stand after successful engine run.