



Photo 1 – Overview of main wreckage.



Photo 2 – View of Right Wing



Photo 3 – View of Left Wing



Photo 4 – View of Damaged Trees



Photo 5 – View of cut tree branches



Photo 6 – View of propeller blade



Photo 7 – View of trees at the departure end of runway 19.