



Photo 1 – View of airplane in nose attitude at wreckage site (Floyd County Police)



Photo 2 – View of propeller at wreckage site, showing gouges in blade and twist.



Photo 3 – View of power lines along tree line in the ravine



Photo 4 – Aerial view of impact point of power line. (Georgia power photo)




Photo 5 – Diagram of power line cable



Photo 6 – Piece of the broken cable (powerline)