

Wartungsübersicht / Maintenance record

Datum: Date:	Betriebsstunden: Engine hours:		Durchgeführte Arbeiten: Work performed:	Unterschrift & LFZ Wart Nr.: Signature & Licence no.:
	Gesamt: TSN:	seit letzter GÜ.: TSO:		

31

Date: 11 March 2021

N708JM

S/N 06 08 09

AC Total Time: 687.2

Completed annual condition inspection IAW FAR 43 requirements using Flight Design checklist as a guide. Found several exhaust springs were missing safety wire. Safety wired springs and reapplied RVT to dampen vibrations. Cleaned gascolator screen and reinstalled safety wire. Reinstalled safety wire on several misc. bolts in the engine compartment. Checked all fluids and filters. Tightened throttle friction to prevent throttle moving in flight. I certify that this aircraft has been inspected in accordance with an annual condition inspection and was found to be

Auth Sign & Cert.

A&P #