



Photo 1 – View of fire damaged airplane right side.



Photo 2 – View of fire damaged airplane aft.



Photo 3 – View of left side of airplane showing fire damaged fuselage and empennage.



Photo 4 – View of fire damaged airplane froward showing engine, and cockpit.



Photo 5 – View of under right horizontal stabilizer and elevator showing burnt oil streaks.



Photo 6 – View of fire damaged oil and fuel lines on accessory section.