

Overview of accident area and images from accident video

NTSB Investigation: ERA21FA257

Lake witnesses observed airplane overfly prior to pull up




Overview of the accident site



Drag Strip

Accident Site




Drawing of accident airplane model (Source: Airplane Flight Manual)



Frame by frame view of video of accident (Video located in public docket)





Enlarged screen image from the video






Enlarged screen image from the video





Enlarged screen image from the video



Overview of Area

ERA21FA257

Legend

- Accident Site/ Drag Strip
- Departure Airport (W40)
- Home Base



Google Earth

Image Landsat / Copernicus