



Photo 1 – front left quartering view of main wreckage



Photo 2 – Front view of main wreckage



Photo 3 – View of tree tops with broken branches



Photo 4 – wire stuck in waste gate



Photo 5 – close up of wire stuck in waste gate



Photo 6 – View of rear of waste gate