



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21FA318



Photo 1 – View of airplane after recovery from Lake Weir.



Photo 2 – View of instrument panel.



Photo 3 – View of the engine.




Photo 4 – Google Earth image of the ADS-B flight track.