



Photo 1 – Left Side View Airplane at Accident Site



Photo 2 - Right Side View Airplane at Accident Site



Photo 3 – Passenger Seat / Emergency Exit (Seat 2B)



Photo 4 – Cockpit Area including Pilot and Co-Pilot/Passenger Seats



Photo 5 – Main Cabin Door Extended on Flat Bed Truck Post-Recovery



Photo 6 – Main Cabin Lower Door Handle and Locking Pin in Locked Position



Photo 7 - Main Cabin Lower Door Handle and Locking Pin in Unlocked/Open Position



Photo 8 – Main Cabin Door Upper Strike Plate and Lower Latching Bore



Photo 9 – Mid Cabin Looking Forward



Photo 10 – Mid Cabin Looking Aft



Photo 11 – Right Main Landing Gear Tire



Photo 12 – Left Engine



Photo 13 – Right Engine