



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21FA377



Photo 1 – View of Fuselage Facing Approximately Opposite Direction of Travel (Courtesy of Textron Aviation)



Photo 2 – View of Fuselage Left Side (Courtesy of Textron Aviation)



Photo 3 – View of Fuselage Right Side (Courtesy of Textron Aviation)



Photo 4 – View of Angularly Cut Wood Recovered Along Wreckage Path (Courtesy of Textron Aviation)



Photo 5 – View of Camping Equipment and Baggage Recovered from Airplane (Courtesy of Textron Aviation)