



Photo 1 – Airplane at Accident Site (courtesy FAA)



Photo 2 – View of the Oil Leak at Nose Cone (courtesy FAA)




Photo 3 - View of Crankshaft with Crankshaft Plug Missing (courtesy FAA)



Photo 4 – Crankshaft Plug (courtesy FAA)