



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA21LA007

October 14, 2020



Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by Gilmer GA, Sheriff's Office.



Photograph 2² – Accident airplane – front view.



Photograph 3³ – Accident airplane – belly view.

² Photograph provided by Gilmer GA, Sheriff's Office.

³ Photograph provided by Gilmer GA, Sheriff's Office.



Photograph 4⁴ – Accident airplane – right side view.



Photograph 5⁵ – Accident airplane – tail section view.

⁴ Photograph provided by Gilmer GA, Sheriff's Office.

⁵ Photograph provided by Gilmer GA, Sheriff's Office.