



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Left Side View of Main Wreckage (Photo Courtesy of FAA)



Photo 3 – Left Side View of Engine (Photo Courtesy of Florida Air Recovery)



Photo 4 – Right Side View of Engine (Photo Courtesy of Florida Air Recovery)



Photo 5 – Top Spark Plugs (Photo Courtesy of Florida Air Recovery)



Photo 6 – Carburetor Floats (Photo Courtesy of Florida Air Recovery)