



Photo 1 – Overall view of airplane wreckage partially submerged in water. (Courtesy of FAA)



Photo 2 – Left side view of airplane wreckage partially submerged in water. (Courtesy of FAA)



Photo 3 – Closeup of left side of airplane resting in water. (Courtesy of FAA)



Photo 4 – Right forward view of airplane wreckage partially submerged in water. (Courtesy of FAA)



Photo 5 – View of right side of airplane damage after partial recovery from water. (Courtesy of FAA)



Photo 6 – View of left side of rudder and elevator damage. (Courtesy of FAA)



Photo 7 – View of damage to the right-side vertical stabilizer and elevator. (Courtesy of FAA)



Photo 8 – View of cockpit and cabin interior damage. (Courtesy of FAA)



Photo 9 – Photograph of control lock discovered on cockpit floor. (Courtesy of FAA)



Photo 10 – View of dirt mound that was impacted by the right wing. Note main wreckage in background. (Courtesy of FAA)



Photo 11 – View of tire skid marks looking back towards runway 14. (Courtesy of FAA)



Photo 12 – View of airplane tire skid marks in grass looking towards wreckage site. (Courtesy of FAA)