



Photo 1 – Digital Photograph Provided by FAA. Frontal View of the Airplane Following Recovery. Note the Abnormal Position of the Left Wing, Damaged Propeller Blade, and Damage at the Right Wing Tip.



Photo 2 - Digital Photograph Provided by FAA. Left Side View of the Airplane Following Recovery. Note the Damage to Both Left Wing Lift Struts.



Photo 3 - Digital Photograph Provided by FAA. Right Rear View of the Airplane Following Recovery. Note the Damage to the Rudder and Vertical Stabilizer.




Photo 4 - Digital Photograph Provided by FAA. Right Side View of the Engine Compartment Following Recovery. Note the Damage to the Engine Mount.