



Photo 1 – View of airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – Additional view of airplane in brush and trees at the accident site (Photo Courtesy of FAA)



Figure 1 – View of the fuel selector placards, mislabeled. Left was right, right was left (Photo Courtesy of FAA)