




**Photo 1 – View of the gyrocopter at the accident site (Photo Courtesy of FAA)**



**Photo 2 – View of the gyrocopter at the accident site (Photo Courtesy of FAA)**



**Photo 3 – View of fuel actively leaking postaccident from a rubber fuel line (Photo Courtesy of FAA)**