



Photo 1 – Tree Strikes (Photo Courtesy of FAA)



Photo 2 – Main Wreckage (Photo Courtesy of FAA)



Photo 3 – Main Wreckage Recovered (Photo Courtesy of FAA)



Photo 4 – Main Wreckage Recovered – Alternate View (Photo Courtesy of FAA)



Photo 5 – Left Engine And Propeller (Photo Courtesy Lycoming)



Photo 6 – Right Engine And Propeller (Photo Courtesy Lycoming)