



**Photo 1 – Photograph of right side of airplane showing damage to the engine compartment and security fence.
(Courtesy of FAA)**



Photo 2 – Close up view of engine compartment damage. (Courtesy of FAA)



Photo 3 – Photograph of the runway and damage path. Note the separated propeller. (Courtesy of FAA)