



Photo 1 – Digital Aerial Photograph From NC Highway Patrol. View of the Helicopter at the Accident Site.



Photo 2 - Digital Photograph From NC Highway Patrol. Right Side View of the Helicopter At the Accident Site.



Photo 3 - Digital Photograph From NC Highway Patrol. View of the Aft Portion of the Tailboom and Tail Rotor Assembly.



Photo 4 - Digital Photograph From NC Highway Patrol. Close-Up Left Side View of the Fuselage. Note the Damaged Main Rotor Blades and Mast, Tailboom, and Skids.