



Photo 1 – View of airplane upside down at the accident site (courtesy FAA).



Photo 2 – View of the engine damage after the airplane was recovered (courtesy of FAA).



Photo 3 – View of damage to the right wing after the airplane was recovered (courtesy of the FAA).



Photo 4 - View of damage to the left wing after the airplane was recovered (courtesy of the FAA).