



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Nose Section – Courtesy of FAA




Photo 3 – Notebook Entry with Required Inspection Date and Name – Courtesy of FAA




Photo 4 – Notebook Entry with Partial Date, Cylinder Numbers and Compression – Courtesy of FAA



Photo 5 – Fuel Selector



Photo 6 – Pitot Tube



Photo 7 – Propeller and Front of Engine



Photo 8 – No. 1 Cylinder




Photo 9 – No. 1 Top Spark Plug and Adaptor



Photo 10 – Damaged Threads on Adaptor




Photo 11 – Close Up of Damaged Threads on Adaptor



Photo 12 – Interior of Magneto Cover




Photo 13 – Interior of Magneto Case