



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA053



Photo 1 – View of airplane where it came to rest. (Photo Courtesy of FAA)



Photo 2 – View of wreckage from the rear (Photo Courtesy of FAA)



Photo 3 – View of the engine where it came to rest (Photo Courtesy of FAA)




Photo 4 – View of the flight path.